

PLANT ALERT:

Don't let erosion/corrosion compromise safety

Thinning of pipe walls and corrosion of other components in high-purity feedwater and steam systems can have catastrophic consequences. Take time to review the problem and apply some important preventive steps

By Otakar Jonas, Jonas Inc

One year ago, the rupture of a feedwater-pipe section just upstream of the economizer resulted in a fatal accident at a US utility drum-boiler unit.¹ The direct cause of the accident was thinning of the pipe wall, apparently the result of erosion/corrosion. An accident similar in origin and consequences occurred in December 1986 at a nuclear pressurized-water reactor (PWR) unit in Virginia.²

Although such serious accidents are rare, erosion/corrosion is a relatively common occurrence in all types of steam systems. It joins drum-boiler waterwall-tube failures and deaerator cracking as the most extensive and expensive waterside problems encountered at powerplants.


The purpose of this alert is to urge powerplant owners and operators to inspect locations in feedwater and wet-steam components that may be susceptible to wall thinning caused by erosion/corrosion. (An extensive list of references is provided for assistance in obtaining background information.)

Also known as flow-assisted corrosion, or FAC, erosion/corrosion is a relatively slow damage mechanism that can lead to rupture before detection—"break before leak" in industry parlance. It occurs in piping when high flow velocity, temperature, and turbulence interact with the chemical environment to promote dissolution of the protective metal oxide present on carbon and low-alloy steel surfaces. This usually occurs in carbon steel components under slightly acidic conditions, with zero or low O₂ concentrations or with excess O₂ scavenger.

Reported experience

Break-before-leak is rare. Usually massive and destructive, it is always the unexpected failure of a component weakened by corrosion (thinning or cracking) or material degradation (creep, graphitization, embrittlement, etc). It results when a large section of pipe or pressure vessel is almost uniformly weakened, or when the normal pressure and/or other stress factors suddenly increase. The 1986 failure of a carbon steel elbow in a feedwater-line brought the problem into sharp focus (see sketch). This prompted inspection of all US nuclear

PWR units and many fossil-fired units, as well as widespread



Catastrophic rupture of 18-in.-diam elbow in main boiler-feedpump suction at Surry-2 (December 1986) resulted from erosion-corrosion. Phenomenon reduced 0.50-in. wall thickness to 0.048 in. locally, 0.09 in. in larger areas

investigation of the erosion/corrosion mechanism.³⁻⁶

Erosion/corrosion has been recognized as a problem in steam-generation systems

for over half a century. The earliest documented occurrence was in industrial steam/condensate-return lines, where low-pH condensate was responsible for grooving and other forms of material removal in carbon and low-alloy steel pipe.^{7,8}

As summarized in Table 1, both fossil-fired and nuclear plants have experienced erosion/corrosion in feedwater heaters (tubes and shells), condensers, feedwater and wet-steam piping, and steam turbines of all types^{5,9-11}; PWR units encounter erosion/corrosion of wet-steam and feedwater piping,^{5,12-16} moisture-separator chevrons,¹⁶ and feedwater inlets in steam generators.¹⁷ Erosion/corrosion has also been a frequent problem in heat-recovery steam generators (HRSGs) used in combined-cycle systems.

Compounding the problem, iron oxides resulting from erosion/corrosion contribute to scale formation in boiler tubes of fossil-fueled units and to sludge formation in PWR steam generators.

Utility experience with erosion/corrosion in nuclear plants was highlighted by a survey conducted for the Nuclear Regulatory Commission in 1987.⁵ Of the responses received from 28 units in the US and Germany, 12 reported erosion/corrosion in feedwater piping, eight in steam-generator inlets (J-tubes and feedwater-distribution rings), and 27 in wet-steam piping (Table 2).

Industry guides

Reduced operating reliability attributed to erosion/corrosion prompted development of inspection and other guidelines

for the industry, including several computer codes to help spot developing trends.^{12,18,19} These focus on the following parameters, found to influence wall thinning of carbon steel pipe as a result of erosion/corrosion:

- Chromium, copper, and molybdenum content.
- Water and steam composition (O₂ or scavenger and pH).
- Temperature.
- Component geometry.
- Flow velocities (which, primarily for economic reasons, have steadily increased over the past three decades, often to double or triple the temperature-related design values recommended by the Heat Exchange Institute).

Relationships between these parameters and erosion/corrosion rates are known quantitatively. What is not known accurately are the effects of reducing conditions caused by excessive concentrations of O₂ scavengers and the effects of some new water treatment chemicals, such as chelating agents and polymeric dispersants and their decomposition products.

Because reducing conditions are known to accelerate erosion/corrosion, eliminating O₂ scavengers during normal operation can significantly reduce feedwater iron concentrations in steam cycles.²⁰ The beneficial effect of low O₂ concentrations in feedwater is also supported by laboratory data, which show that increasing feedwater O₂ above 4 ppb can stop erosion/corrosion. The excellent experience of hundreds of utility units using oxygenated treatment (OT) for high-purity feedwater attests to this improvement.²¹

Precautionary measures

Based on the information available, adoption of the following procedures is strongly recommended:

1. Carbon steel piping and other components operating with hot water and wet steam should be inspected for wall thinning by erosion/corrosion as soon as practical (and periodically thereafter). While 100% inspection is not necessary, priority should be given to components with low chromium content subjected to high flow velocity, low pH, and low O₂ operating in the temperature range 250 to 350F—particularly those with geometries susceptible

to this damage mechanism.

2. Such susceptible locations and components should be evaluated using CHECMATE, the accepted computer code.¹⁸

3. Ultrasonic techniques or radiography can be used to measure wall thickness.

4. If wall thinning from erosion/corrosion is encountered, the problem can be resolved by optimizing water chemistry and/or replacing carbon steel components with steels of higher chromium content. To avoid break-before-leak, maximum stresses and pressures rather than normal (or nominal) operating conditions should

be used to determine minimum allowable wall thicknesses.

5. In evaluations of water chemistry, the at-temperature pH values and pH_T of moisture droplets should be used.

6. When new water treatment chemicals and O₂ scavengers are used, their impact and that of their decomposition products on the erosion/corrosion mechanism should be evaluated.

Edited by Sheldon Strauss

Table 1: Erosion/corrosion reported in steam-cycle components*

Component	Cycle		
	Fossil-fuel	Industrial	PWR BWR
Feedwater heaters	X	X	X X
Condensers	X	X	X X
Wet-steam piping	—	X	X —
Feedwater piping	X	X	X —
Condensate-return lines	X	X	— —
Moisture separators	—	—	X X
J-tubes	—	—	X —
Economizers	X	X	— —
Deaerators (vertical)	X	—	— —
Desuperheater liners	X	X	— —
L-p-turbine discs	—	—	X —
H-p-turbine casings	—	—	X —
Turbine-gland areas	—	X	X X
HRSGs	X	X	— —

*Sources: References 5, 12-18

Table 2: Occurrence of erosion/corrosion in nuclear PWR cycles¹

Unit	Utility	Years in service ²	System	
			Water	Steam
Beaver Valley-1	Duquesne Light Co	11	No	Yes
Calvert Cliffs-1	Baltimore Gas & Electric Co	12	Yes	Yes
Calvert Cliffs-2	Baltimore Gas & Electric Co	10	Yes	Yes
Crystal River-3	Florida Power Corp	10	No	Yes
Fort Calhoun	Omaha Public Power District	14	Yes	Yes
Indian Point-2	Cosolidated Edison Co of NY	14	No	Yes
Indian Point-3	New York Power Authority	11	No	Yes
Kewaunee	Wisconsin Public Service Corp ³	13	No	Yes
Oconee-1	Duke Power Co	14	No	Yes
Oconee-2	Duke Power Co	13	No	Yes
Oconee-3	Duke Power Co	13	No	Yes
Palisades	Consumers Power Co	15	No	Yes
Rancho Seco	Sacramento Municipal Utility District	13	Yes	Yes
H B Robinson-2	Carolina Power & Light Co	17	No	Yes
Salem-1	Public Service Electric & Gas Co	10	Yes	Yes
Salem-2	Public Service Electric & Gas Co	6	Yes	Yes
San Onofre-1	Southern California Edison Co	19	Yes	Yes
San Onofre-2	Southern California Edison Co	4	Yes	Yes
San Onofre-3	Southern California Edison Co	3	Yes	Yes
Surry-1	Virginia Power	15	Yes	Yes
Surry-2	Virginia Power	14	Yes	Yes
Trojan	Portland General Electric Co	11	Yes	Yes
Turkey Point-1	Florida Power & Light Co	15	Yes	Yes
Turkey Point-2	Florida Power & Light Co	14	Yes	Yes
Zion-1	Commonwealth Edison Co	14	Yes	Yes
Zion-2	Commonwealth Edison Co	13	Yes	Yes
Neckar-1	GKN (Germany)	11	No	Yes
Brokdorf	KBR (Germany)	1	No	No

¹Source: Reference 5 ²As of time of survey ³With Wisconsin Power & Light Co and Madson Gas & Electric Co, non-operating co-owners

References

- 1 S A Patulski, "Pleasant Prairie Unit 1 Feedwater Line Failure," report to FOMIS, June 1995
- 2 "Surry Power Station Unit 2 Reactor Trip/Feedwater-Pipe Failure Report," Virginia Power, presented to NRC Region 1 at King of Prussia, Pa, Jan 14, 1987
- 3 O Jonas, "Control Erosion/corrosion of Steels in Wet Steam," POWER, March 1985, p 102
- 4 EPRI Workshop on Erosion/Corrosion of Carbon Steel Piping, Nuclear and Fossil Plants, Washington DC, April 1987
- 5 O Jonas, "Erosion/corrosion of PWR Feedwater Piping—Survey of Experience, Design, Water Chemistry, and Materials," Report for US Nuclear Regulatory Commission, Nureg CR-5149, ANL-88-23, March 1988
- 6 W J Shack and others, "Investigation of Erosion/corrosion in Reactor Piping," US NRC/MITI Workshop on Nuclear Power Safety Systems, Tokyo, Japan, May 1988
- 7 M E Dreyfus, "Controlling Corrosion in Steam and Return Lines," Power Plant Engineering, April 1938
- 8 A A Berk, "Treating Steam Chemically to Reduce Return Line Corrosion," Industry & Power, November 1947
- 9 S Takahashi and T Horiuchi, "Hydraulic Impact Forces Causing Waterside-Inlet Impingement Attack on Carbon Steel Tubed, High-Pressure Feedwater Heaters," ASME Winter Annual Meeting, New York, NY, November 1969
- 10 J M Decker and J C Marsh, "Evaluation of Several Alkaline Compounds for Controlling Corrosion-Erosion in Boiler Feedwater Systems," American Power Conference, April 1954
- 11 I Inusa, "Elbow Failure at Navajo Generating Station due to Erosion/corrosion," EPRI Workshop on Erosion/corrosion of Carbon Steel Piping, Nuclear and Fossil Plants, Washington DC, April 1987
- 12 "Erosion/corrosion in Nuclear Plant Steel Piping: Causes and Inspection Program Guidelines," EPRI NP-3944 Final Report, April 1985
- 13 R Svoboda and G Faber, "Erosion/corrosion of Steam Turbine Components," from "Corrosion in Power Generating Equipment," Plenum Press, 1984, p 269
- 14 M J Fountain and others, "Two-Phase Erosion/corrosion Studies at CEGB Northwestern Region," International Water Conference, Pittsburgh, Pa, October 1984
- 15 H G Heitman and W Kastner, "Erosion/corrosion in Water-Steam Circuits—Causes and Countermeasures," VGB Kraftwerkstechnik 62, 1982
- 16 "Nuclear Power Experience," RCC/Hagler Bailly Inc, Boulder, Colo
- 17 B C Bignold and others, "Erosion/Corrosion in Nuclear Steam Generators," Second International Conference on Water Chemistry of Nuclear Reactor Systems, Bournemouth, UK, October 1980
- 18 S M Walker and F V Ammirato, "Non-Destructive Examination of Ferritic Piping for Erosion/corrosion," EPRI RP-1570-2, April 1987
- 19 EPRI "ChecMate Computer Program for Erosion/corrosion Analysis," EPRI, Palo Alto, Calif, April 1991
- 20 R B Dooley and others, "Optimum Chemistry for All-Ferrous Feedwater Systems: Why Use an O₂ Scavenger?" International Water Conference, Pittsburgh, Pa, October 1994
- 21 "Cycle Chemistry Guidelines for Fossil Plants: Oxygenated Treatment," EPRI Report No. TR-102285, December 1994